## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**


Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


## IMAGES ARE BEST AVAILABLE COPY.


As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.


























LIFT @ DOOR HT. E LIFT CONTROLLER OUTPUT ... OPEN DOOR = 1 170 15 NO DOOK CLOSEO? YES -172 IS No DOOR CATCHED? 4ES ACTIVATE ACTIVATE PLUE 174 UN -LATCH UN-PLUG MOTOR 176. SOLENDID TO PLUG POSITION 178 15 No DOOR .. UN-LATCHED) 465 ACTIVATE PLUG/ 180 UN-PLUC MOTOR TO UN-PLUC POSITION 182 15 NO DOOR UN-PWELED YES ACTUATE DOOR OPEN/CLOSE 184 HOTOR TO CREA POSITION. ís 186 DOOR FULLY OPEN YES Fig. 18 11 DE-ACTIVATE -188 OPENICLOSE MOTOR OUTPUT DOOR OPEN SIGNAL TO

LIFT CONTROLS

LIFT @ DOOR HT. & LIFT CONTROLLER DUTPUT DUTPUT = CLOSE DOOR=1 190 DOOR NOT CLOSED YES 192 NO DOOR UNPLUCTED 4ES ACTUATE DOOR 194 OPENICLOSE MOTOR TO "CLOSE" POSITION -196 13 YES DOOR BLOCKED? ACTIVATE DOOR OPEN/CLOSE MOTOR No -198 to OPEN POSITION ้เร DOOR FULLY υO 1551 DOOK FULLY CLOSED ? OPEN -202 -200 YES YES ACTUATE PLUG! UN-FLUE MOTOR 204 TO PULL POSITION 13 DOOR NO LATCHED 206 YES OUTPUT DOOK LATCHED - 208 SIGNAL to LIFT CONTROL CIRCUIT END.

WHEET ? DE CO

Fig. 1812

